

ATTACHMENT 6
Reference Data and Reports for Independent Remedial Actions, Pre-1998

Boeing Commercial Airplanes, Fabrication Division – Auburn Plant

- 17-07: Alkaline Waste Hold Tank*; Kennedy -Jenks; October, 1994; (57)
- 17-05: Closure Report*; Kennedy-Jenks; June, 1994; (63)
- 17-05: Waste Hold Tank Analysis*; Kennedy-Jenks & ARI; 1994; (64)
- 17-07: Results of Site Characterization*; Kennedy-Jenks; May 23, 1994; (67)
- 17-07: Final Closure Report*; Kennedy-Jenks; September 14, 1994; (68)
- 17-07: Closure Report, Waste Hold Tank*; Kennedy-Jenks; December, 1993; (69)
- 17-07: Supplemental Closure Report*; Kennedy-Jenks; July 20, 1994; (70)
- 17-06: Subsurface Assessment of 2 USTs*; GeoEngineers; May,23, 1991; (72)
- Removal of Methyl Ethyl Ketone UST*; GeoEngineers; April 7, 1992; (76)
- 17-29: Sump Tank Removal & Replacement*; GeoEngineers; May 23, 1991; (82)
- UST Groundwater Monitoring; Dames & Moore*; 1987-1992; (91)
- Soil Sampling for USTs; Norton Corrosion Ltd., Inc.*; November 30, 1985; (92)
- 17-07: Subsurface Investigation*; Kennedy-Jenks; May, 1996; (94)
- Hydrogeologic Investigation & Summary*; Kennedy-Jenks; May, 1996; (96)
- Government Canal – Independent Remedial Action*; Charlton & Leach; January 20, 1995; (110)
- Government Canal – Phase II Investigation*; GeoEngineers; October 7, 1992; (111)
- Government Canal – Drainage Assessment*; Tetra Tech, Inc.; November 25, 1991; (113)
- Government Canal – Drainage System, Preliminary Assessment*; Tetra Tech, Inc.; February 10, 1992; (114)
- 17-66 Hydrogeologic Investigation*; Kennedy-Jenks; January, 1994; (117)
- Hydrogeologic Investigation Rinsewater Treatment Plant Area*; Kennedy-Jenks; January, 1994; (123)

ATTACHMENT 6
Reference Data and Reports for Independent Remedial Actions, Pre-1998

Boeing Commercial Airplanes, Fabrication Division – Auburn Plant

- Environmental & Compliance Monitoring Report - Rinsewater Treatment Plant;*** Kennedy-Jenks; January, 1993; (124)
- 17-03: Environmental Monitoring Report;*** Kennedy-Jenks; January, 1993; (128)
- 17-02, 17-05; Demolition Projects;*** Kennedy-Jenks; May, 1994; (133)
- 17-10: Soil Excavation Monitoring; Landau Associates;*** July 18, 1990; (142)
- 17-52: Battery Wash Pad Assessment;*** Hart Crowser, Inc.; November, 1987; (145)
- 17-06 Drilling Additional Soil Borings;*** GeoEngineers; April 6, 1992; (147)
- 17-34: Sump & Contaminated Soil Removal;*** Hart Crowser, Inc.; July 11, 1986; (155)
- 17-34: Hazardous Waste Storage Facility Assessment;*** Hart Crowser, Inc.; May 15, 1986; (156)
- 17-08: Environmental Response Action;*** Kennedy-Jenks; February 22, 1994; (157)
- Underground Storage Tank #31 & #32;*** Auburn Environmental Engineering; March, 1996; (181)
- Exposure Information Report;*** Boeing Commercial Airplane Group; August 30, 1985; (1006)
- Groundwater Data Statistical Review, Volume 1;*** Dames & Moore; June 15, 1988; (1007)
- Groundwater Assessment Plan; Boeing Commercial Airplane Group;*** January 31, 1985; (1012)
- Sludge Pile Delisting Petition;*** Boeing Commercial Airplane Group; November, 1985; (1240)
- Sludge Pile Monitoring Wells;*** U.S. EPA; June 17, 1985; (1244)
- Proposed Detection Monitoring System;*** Dames & Moore; August 30, 1985; (1247)
- South Lagoon Closure Report & Certification;*** Dames & Moore; November 16, 1988; (1251)
- COR, Former North Lagoon;*** BCAG, WDOE, Dames & Moore; 1987 – 1988; (1252)

ATTACHMENT 6
Reference Data and Reports for Independent Remedial Actions, Pre-1998

Boeing Commercial Airplanes, Fabrication Division – Auburn Plant

17-15: Rinse Water Treatment Plant – North Lagoon; Boeing Commercial Airplane Group; November 14, 1986; (1253)

17-15: Rinse Water Treatment Plant – Phase II Closure; Boeing Commercial Airplane Group; July 2, 1987; (1254)

Old North Lagoon Wells; Dames & Moore, BCAG; September 15, 1988; (1255)

Groundwater Monitoring Wells; Dames & Moore, BCAG; 1983; (1258)

Groundwater Monitoring Wells; Dames & Moore, BCAG; 1984; (1259)

4th Quarter Groundwater Monitoring Report; Dames & Moore; August 30, 1988; (1260)

Evaluation of Groundwater Monitoring Data; Geraghty & Miller, Inc.; November, 1985; (1261)

Burn Pit/Tank Area Soil Sampling & Analysis; Dames & Moore; July 17, 1987; (1262)

17-64: Independent Action Cleanup Report; BCAG; May, 1993; (1323)

17-06: Briquetting Machine – Subsurface Assessment; SECOR; September 9, 1996; (1324)

South Lagoon Closure Report; BCAG; December 1, 1988; (1460)

17-15: Volatile Organics in Groundwater at Auburn Facility; Corporate SHEA, Quadrant, Kennedy-Jenks; 1994; (1467)

17-07: RCRA Acid and Cyanide Tank Closures – Final Closure Report; AGI; November 1, 1996; (2046)

17-45: Spray Paint Booths; AMTEST; July 17, 1996; (2056)

17-06: Closure Certification – 66,000 Gallon Waste Hold Tank; January, 1997; (2100)

Underground Storage Tank History; Kennedy-Jenks; April, 1989; (2116)

17-05: Hydrogeologic Investigation; February, 1995; (2119)

17-15: Technical Report – Preliminary Subsurface Investigation Rinsewater Treatment Plant; Kennedy-Jenks; November, 1991; (2121)

Risk Assessment for Boeing Government Canal; McLaren/Hart; August, 1992; (2145)

ATTACHMENT 6
Reference Data and Reports for Independent Remedial Actions, Pre-1998

Boeing Commercial Airplanes, Fabrication Division – Auburn Plant

17-05: Vapor Degreaser Removal; Kennedy-Jenks; April, 1997; (2169)

Building 17-05 Area Hydrogeologic Characterization; Kennedy-Jenks; May, 1997

17-29: Titanium Bailing Area; GeoEngineers; June, 1997